



ERRATA - Half-Track - MODELIK 13/10

The engine block is not parallel to the frame plane. Engine should be glued in such a way that the top edge of part 42 coincides with the edges of the frames 1L and 1P. By using of 2 mm diameter electric conductor make connections between part 19 on the engine body and the upper surface of the radiator, and between the engine block and bottom surface of the radiator (marked with thick black lines in the figure 15).




Rys.15


Blok silnika nie jest równoległy z płaszczyzną ramy. Silnik powinien być wklejony w taki sposób, aby górna krawędź cz.42 pokrywała się z krawędziami ramy 1L i 1P. Z osłon przewodu elektrycznego o średnicy 2 mm wykonać połączenia pomiędzy cz.19 na korpusie silnika i górną krawędzią chłodnic, oraz pomiędzy blokiem silnika a dolną powierzchnią chłodnicy (na rys.15 grube czarne linie)





Rys.47



Rys.3



KSZTAŁT PODŁOŻY PRZEDZIAŁU DESANTOWEGO



Rys.1

